


| Evaluation Tracked Excavator | | www.mevas.eu  | |
|---|---|---|--|
| Customer/location: | Bavaria Swiss/Plattling | vers 02-20 | |
| Date: | 04.11.2021 | | |
| Machine / type: | CAT 325F | Hour reading: | 6355 |
| Serial No.: | YCA00254 | Year: | 2016 |
| Inspector: | WB | stick length: | 2,95m |
| CE label <input checked="" type="checkbox"/> | boom check valve <input checked="" type="checkbox"/> | adjustable boom <input type="checkbox"/> | DPF <input checked="" type="checkbox"/> DEF (AdBlue) <input checked="" type="checkbox"/> |
| auto lube <input type="checkbox"/> | stick check valve <input checked="" type="checkbox"/> | stabilizer blade <input type="checkbox"/> | A/C <input checked="" type="checkbox"/> |
| lines hammer <input checked="" type="checkbox"/> | lines grapple/shear <input checked="" type="checkbox"/> | quick coupler type: | Winkelbauer hydraulic |
| cab | | cab door, covers | good |
| seat, arm rests | good | windows & mirrors | good |
| switches, joysticks | good | wipers, washer | good, wiper blade worn |
| gauges & warn lights | good | floor mat | good |
| aircon / heater | good | cab structure | good |
| engine | | Serial No. | |
| leaks & seals | no leaks seen | cooling system | good |
| oil condition & level | good/good | blow by | normal |
| exhaust, muffler | good | belts & filters | good |
| smoke | normal | coolant condition | good |
| visual inspection exterior | | covers / sheets | good |
| chassis, track frame | | side doors | good |
| engine hood | good | compartments | good |
| steps, hand rails | two steps slightly bent | bumpers / catwalk | good |
| boom | good | lights, batteries | good |
| stick | good | paintwork | good |
| hydraulics | low hydraulic oil level | boom cylinders | good |
| hoses, lines, swivel | good | stick cylinder | good |
| pump and valve bloc | good | bucket cylinder | good |
| functional test | | boom self drift | none |
| pins boom | moderate play | pump noises | good |
| pins stick | moderate play | slew ring play | good |
| pins bucket | moderate play | electric system | good, 1) |
| swing drive/brake | good | drive train | good |
| tools | | bucket 2, size, type | - |
| bucket 1, size & type | 1,25m GP | condition | - |
| condition | 60% remaining life | coupler condition | some play to bucket |
| U/C | remaining life mm (%) | rollers | 80% |
| bushings | 80% | track links | 70% |
| shoes | 70% | sprockets | 70% |
| idlers | 80% | track pitch in mm: | 768 |
| carrier rollers | 80% | shoe width in mm: | 600 |
| problems, details | | | |
| Machine is equipped with reverse camera | | | |
| Minor dent on sheet front RHS | | | |
| 1) lift limitation sensor on boom disengaged. (pict 283) | | | |
| The machine is in good condition. No major problems seen. | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| dimensions for transport L x W x H in meter: | 8,85 x 3,0 x 3,3 | | |