Evaluation Wheel Loader		www.mevas.net	
Customer:	*Bavaria Swiss*	vers 12-24	
Date:	*25.02.2026*		
Machine / type:	*CAT 966MXE*	location:	*Germany*
Serial No.:	*DZL00676*	Hour reading:	*10.448*
Inspector:	*WB*	Year:	*2020*
CE ☑ A/C ☑	EPA ☐ Auto-Greaser ☑	Hydrostat ☐	quick coupler ☑
3rd valve ☐	supplemental steering ☑	weigh load ☐	Parts book ☐ Op-Manual ☐
cab		cab door	*good*
seat, arm rests	*good*	windows, mirrors	*good*
switches, levers	*good*	wipers, washer	*good*
gauges & lamps	*good*	floor mat	*good*
aircon / heater	*good, good*	cab structure	*good*
engine			
leaks & seals	*no leaks seen*	Serial No.	
oil condition & level	*good*	DPF&DEF status	*good*
exhaust, muffler	*good*	cooling system	*good*
smoke	*normal*	belts & filters	*good*
blow by	*normal*	coolant condition	*good*
exterior		counterweight	*good*
chassis & lift arm	*good*	fenders	*RHS front shop-repaired*
engine hood	*good*	lights, batteries	*good*
stairs, hand rails	*good*	paintwork	*peeling on engine hood*
power train		rims, wheel nuts	*good*
axles/differentials	*good*	universal joints	*good*
gearbox	*minor seepage LHS*	transfer gear	*good*
power train	*good*	transm. noises	*good*
hydraulics		steering cylinders	*RHS leak*
hoses & lines	*good*	pumps & valves	*good*
lift & tilt cylinders	*good*	steering orbital	*good*
functional test	full bucket lift in seconds:		
steering	*good*	articulation play	*good*
transmission test	*good*	loader pins	*good*
stall test	*good*	electric system	*good*
brake / park brake	*good*	supplem. steering	*good*
bucket	*GP bucket with teeth*	width / capacity	*2,99m / 4,2m³*
edges / teeth	*60% good*	side condition	*60% good*
bottom	*60% good, back a bit bumpy*	quick coupler	*CAT-hydraulic*
tires	**mm (%) good**	**size, brand, comments**	
front right	*24mm (35%)*	*26.5R25, Goodyear E-4 6S*	
front left	*24mm (35%)*	*26.5R25, Goodyear E-4 6S*	
rear right	*19mm (30%)*	*26.5R25, Goodyear E-4 6S*	
rear left	*21mm (30%)*	*26.5R25, Goodyear E-4 6S*	
problems, details:			
Minor seepage on transmission LHS. Transmission oil level a bit low.			
Hydraulic oil a bit low.			
The machine is in good condition. No major repairs required.			
transport dimensions L x W x H in meter:	*W 3,00m*		

© 2022 | MEVAS | Liability for hidden defects excluded.
Terms/Conditions: www.mevas.net/legal-documents/imprint